ENDANGERED SPECIES OBSERVER PROGRAM


Project: 22 of Simon's Channel, Pronswick GA

## INCIDENT REPORT OF SEA TURTLE TAKE BY DREDGING ACTIVITY

* * * * * * * * * * * * * * * * * * *	e(24hr)
Species of Turtle Taken Carette	a caretta)
Dredging Site (channel, port, etc.)ain+ Simon's	Channel, Brunswick, Georgia
Location of Take: Latitude N 31 05 78.19 .	Longitude W 81°18 52.59
Vessel Name and Company Manson	
Type of Dredging Activity Maintenance	
Load # Times: Start O9 4	
Sampling Method (overflow, inflow, etc.)	av (I-w)
Samples Recovered From	
Condition of Screening Octob	
Draghead Deflector? Yes No	
Condition of DeflectorQood	
Weather Conditions What Ne Atten Sens of	clim kins hazy Tide 5.9 ebbing
Water Temperature: Surface Column	C or F (circle one)
Condition of Specimen(s) Sampled Rear Hopers (	connected) deedged up and found in
port inflow. Cuticle intact on flippers. Bon	es connected appeared sandblasted.
Muscle fissue is pink - 10 dapping blo	ed. Specimen was frozen.
Measurements	
Give estimate of entire carapace dimensions, as well as fragm	ents sampled (in metric when possible, indicate if not):
Head Width	
Plastron Length N/h	Width
	S.L. Width
	O.C. Width
Turtle Tagged? Yes No Tag#_	
Comments	
We estimate that the death of th	is individual occurred within the last
24 hours or so. There have been up	to 13 shrimp trawlers Working
in and around the channel in the	
attribute the death of this turtle to de	
Observer's Name Macking M. Pierry	v /

Shade areas of turtle which are missing. Sketch cracks and lacerations.

Date 01-03-99	
species Loggerhead	
Time found 1000	
load # 152	
vessel name: Newbort	
Company: Manson	
H.D. teno: 54° F	



Flippers connected by tissue and a few bones only. Bones appear sandblasted. Muscle pink - no dripping blood.

